## **Under Review Notification**

Raised By: Steven Drouin

Product #: D130-1023

Date: 19.07.30

Product Name: OEM SKIDTUBE TRAINING WEARPLATE

		"Y" or "N" Required for Each Part Do not leave blank								
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)		Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
D350-1023-011	IIN-D350-1023 Rev. B	Ÿ	Υ	N	Υ	N	Υ	Υ	19-831	CHG 001
D5404-041	D5404 Rev.B	Υ	Υ	N	Υ	N	Υ	Υ	19-831	Drawing Update
D5404-042	D5404 Rev. B	Υ	Υ	Ν	Υ	N	Υ	Υ	19-831	Drawing Update
								L_		
			ļ			ļ	ļ			
								_		
				-		<b></b> -	<b>-</b>	$\vdash$		

Description of Issue:

Current attachment to fwd saddle on outboard side prone to buckling. New design will attach on both sides to prevent this.

SALES: Do not quote, wait for new design

Distribution:

**VP** Operations

Director of Operations

Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer

Engineering Project Managers Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider Supply Chain Director / Senior Buyer

Marketing Eugene

H:\Forms\Engineering\Approved ENG Online\URF revG.xls

## **Linda Lacelle**

From:

Linda Lacelle

Sent:

Wednesday, July 31, 2019 7:27 AM

To:

John Chuprun; Marcel Daviau; Patrick Duval; Rachel Maloney

Cc:

Jennifer Renwick; Jean-Luc Menard; David Duval; Pablo Bravo; Steven Drouin; Konrad Sauve; Michael Lee; Michelle

GagnonDonovan; Nazim Ould-Brahim; Robert Aboud; Victoria Seib

Subject:

RE: URF19-831

W/o's deleted (no wip)

D5404-1 – 6 stk – ST041 D5404-2 – 1 stk – WA002-2

D350-1023-011 – 1 stk – European warehouse

L

From: Steven Drouin <sdrouin@dartaero.com>

Sent: Tuesday, July 30, 2019 4:42 PM

To: Pablo Bravo <pbr/>pravo@dartaero.com>; Chantal Lavoie <clavoie@dartaero.com>; DART SALES ASIA PACIFIC <dartsalesasiapacific@dartaero.com>; DART SALES EMEA RUSSIA <dartsalesemearussia@dartaero.com>; DART SALES LATIN AMERICA <dartsaleslatinamerica@dartaero.com>; DART SALES NORTH AMERICA <dartsalesnorthamerica@dartaero.com>; David Duval <dduval@dartaero.com>; David Shepherd <dshepherd@dartaero.com>; Frederick Leblanc <fleblanc@dartaero.com>; Jean-Luc Menard <jmenard@dartaero.com>; Jennifer Renwick <jrenwick@dartaero.com>; John Chuprun <jchuprun@dartaero.com>; Konrad Sauve <ksauve@dartaero.com>; Linda Lacelle <llacelle@dartaero.com>; Marcel Daviau <mdaviau@dartaero.com>; Marie Lajeunesse <mlajeunesse@dartaero.com>; Michael Lee <mlee1@dartaero.com>; Michelle GagnonDonovan <mgagnondonovan@dartaero.com>; Nazim Ould-Brahim <nouldbrahim@dartaero.com>; Patrick Duval <pduval@dartaero.com>; Robert Aboud <raboud@dartaero.com>; Steven Hemmerich <shemmerich@dartaero.com>; Support <support@dartaero.com>; Support Eugene <support.orrestored@dartaero.com>; Victoria Seib <vseib@dartaero.com>; Wesley Reid <wreid@dartaero.com>

Subject: URF19-831

Hello,

Please be advised that D350-1023, OEM SKIDTUBE TRANING WEARPLATE are now under review per attached form.